


Control Room Corrosion Pre-Monitoring Studies



<0.1 microns

No failures found

>0.1 microns

Intermittent failures in 1-2 years

>0.4 microns

Inoperative in 2-4 years

>0.6 microns

Intermittent failures in 0.5-1 years

>2.0 microns

Inoperative in 0.25-0.5 years